DNV

SURVEY REPORT

DNV Id No:
NA

Name of Ship: **Kostervåg SLTA**

Owner:

Upon request from Oma Slipp " Mek. Verksted AS the undersigned carried out bottom survey of MS Kostervåg, on the slipway at Oma Slip, Stord 2025-05-14

Bottom bilge and side plating surveyed and found in order.
Bottom valves in engine rooms were opened, inspected and found in order (2 off).
Propeller, brackets, rudder, inspected and found in order .

Clearences measured:

PS rudder bearing (upper bearing)	0,15 mm
PS rudder bearing (lower bearing)	0,15 mm
PS shaft bracket (aft)	0,25 mm
PS Shaft bracket (forward)	0,20 mm
PS sterntube bearing	0,15 mm
STB rudder bearing (upper bearing	0,15 mm
STB rudder bearing (lower bearing	0,15 mm
STB shaft bracket (aft)	0,15 mm
STB shaft bracket (forward)	0,20 mm
STB sterntube bearing	0,20 mm

Issued at **Stord** on **2025-06-24**

for **DNV**

Asbjørn Dahle
Surveyor