

Firma

Hirtshals Yard A/S
Jens Munksvej 1
9850 Hirtshals

Service Report - Engine

Side: 1/2
Ordrenr.: 180690
Udfyldt af: ML
Godkendt af: ML
Godkendt (dato): 30-09-2021
Rekvirent: Henrik Jensen
Reference: Idefix

ENGINE SPECIFICATION

Engine no.	Make	Model	Use	Running hours
-	-	-	-	-

GENERATOR 1 - CATERPILLAR C18:

ESN: CYG00647

Running hours: 9355

Observations: Minor leakages at water pump.

Nothing abnormal observed.

No fault during diagnostic test.

Major overhaul to be performed at 10.000 running hours.

GENERATOR 2 - CATERPILLAR C18:

ESN: CYG00646

Running hours: 13280

Observations: Minor leakages at water pump.

Nothing abnormal observed.

No fault during diagnostic test.

We recommend to check that major overhaul was performed at 10.000 running hours.

MAIN ENGINE - CATERPILLAR C32

ENSN: RNY02129

Running hours: 11448

Observations: Minor water leakages.

Nothing abnormal observed.

No fault during diagnostic test.

We recommend to check if top end overhaul was performed at 10.000 running hours.

EMERGENCY GENERATOR - CATERPILLAR C4.4DITA

ESN: J1Z04944

Running hours: 8719

Observations: Minor water leakages. Minor fuel leakages from cylinderhead. Oil leakage at flywheel (damaged seal or high crankcase pressure).

Nothing urgent observed.

We recommend to check that crankcase breather was replaced at 8.000 running hours

Deutz MVM:

ENS: 604.08.010351

Running hours: 14125.

Observations: Connections for inlet flaps broken.

Minor exhaust leakage observed at start.

Nothing abnormal observed.

Picture and Product Status Report attached.

Firma

Hirtshals Yard A/S
Jens Munksvej 1
9850 Hirtshals

Service Report - Engine

Side: 2/2
Ordrenr.: 180690
Udfyldt af: ML
Godkendt af: ML
Godkendt (dato): 30-09-2021
Rekvirent: Henrik Jensen
Reference: Idefix